



Lenovo IdeaPad U450 Screen Replacement

This guide will take you through the steps to replace a damaged screen for the Lenovo IdeaPad U450.

Written By: Rachel L Rodrigues



INTRODUCTION

This guide will take you through the steps to replace a damaged screen for the Lenovo IdeaPad U450.




TOOLS:

- [Phillips #00 Screwdriver](#) (1)
 - [Spudger](#) (1)
-


Step 1 — Battery




 Turn off and unplug your laptop to prevent the risk of electrocution.

- Turn your laptop over so that the bottom is face up.

Step 2



 On the top left of the laptop there is a switch. Make sure it's pushed in the unlocked position.

Step 3




- Locate the switch collinear with the last one and move the switch to an unlocked position.

Step 4



- Remove the unlocked battery.

Step 5 — Screen



- Open the laptop.

Step 6



- Remove the four 7mm phillips head screws in the corners of the screen with a Phillips #00 Screwdriver.

Step 7




- Pry the screen out of the tabs with a spudger.

Step 8



- Remove the four 7mm phillips head screws located beneath the screen.

Step 9



- Pop out the connector that links the screen to the motherboard.

Step 10



- Pop the new screen into the connector.

To reassemble your device, follow these instructions in reverse order.

This document was last generated on 2017-06-24 05:44:45 AM.